

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6





FIG. 7



## FIG. 8




FIG. 9






FIG. 10



# FIG. 11



## FIG. 12



Move the movable linkage member away from the region between the first and second arm portions to form an air gap between the first and second arm portions

196

End